



NOTAM Detail

DATE: 05/08/2023 04:07
 KEYS: LOCATION: RJSN
 PERIOD: [23/05/11 00:00] - [23/05/13 08:00]
 NOTAM CODE: RT
 SCOPE: A,E,W,AE,AW,EW

New :Issued within 24 hours  :Urgent [to AIP-SUP](#) :Linked AIP-SUP

New 080302 RJAAYNYX
 (0576/23 NOTAMN
 Q)RJJJ/QRTCA/IV/BO/AW/000/030/3755N13904E001
 A)RJSN B)2305110000 C)2305130800
 E)ALL VFR ACFT ARE REQUESTED TO AVOID FLYING THE FLW AREA AS FAR AS
 POSSIBLE IN ORDER TO PREVENT AN UNSAFE CONGESTION OF ACFT AND SECURE
 THE VIP.

1.AREA : WI A RADIUS OF 1000M FM TOKIMESSE
 (375536.9N1390337.8E)
 (APRX QTE/235DEG 3.0NM FM RJSN ARP)
 (NIIGATA-SHI)


2.AREA : WI A RADIUS OF 500M FM HOTEL OKURA NIIGATA
 (375511.6N1390303.8E)
 (APRX QTE/233DEG 3.6NM FM RJSN ARP)
 (NIIGATA-SHI)

3.AREA : WI A RADIUS OF 500M FM ANA CROWN PLAZA HOTEL NIIGATA
 (375506.3N1390333.0E)
 (APRX QTE/228DEG 3.4NM FM RJSN ARP)
 (NIIGATA-SHI)

EXCEPTION :

(1)ACFT ON PATROL MISSION OPERATED BY POLICE AND JAPAN COAST GUARD
 (2)ACFT ON URGENT MISSION FOR FIRE FIGHTING AND RESCUE
 (DOCTOR HEL, JAPAN SELF DEFENCE FORCE ACFT, ETC)
 (3)ACFT UNDER ATC INSTRUCTIONS OR APPROVALS IN CONSIDERATION OF
 WX COND, TFC SITUATIONS OR AP/AD FOR LDG AND TKOF
 (4)ACFT WITH PRIOR COORDINATION WITH POLICE

RMK: NIIGATA PREFECTURAL POLICE
 TEL:025-285-0110 (EXTENSION 6423)
 F)SFC G)3000FT AMSL)



Contact us | Policy

Copyright©Ministry of Land, Infrastructure, Transport and Tourism

