## AIS JAPAN Japan Aeronautical Information Service Center



## **NOTAM Detail**

DATE: 10/24/2025 02:43 KEYS: SCOPE: A,E,W,AE,AW,EW

ITEM-E: 354007

New :Issued within 24 hours 🕴 :Urgent 🔀 to AIP-SUP :Linked AIP-SUP

**New** 240233 RJAAYNYX (7392/25 NOTAMN

Q)RJJJ/QXXXX/IV/BO/W/000/080/3540N13945E030

A)RJJJ B)2510270600 C)2510290200

E)ALL ACFT ARE REQUESTED FLW FLT PROCEDURES DUE TO THE VISIT OF

THE PRESIDENT OF THE U.S. TO JAPAN

1.AREA: WI A RADIUS OF 30NM OF THE U.S. EMBASSY

(354007.04N1394435.47E) (MINATO-KU IN TOKYO)

2.PROC: (1) ACTIVATE ATC TRANSPONDER

(2) FILE FPL TO APPROPRIATE AIRPORT OFFICE

(3) MNTN COM WITH ATC UNIT FOR RECEIVE RADAR ADVISORY SER

F)SFC G)8000FT AMSL)

Contact us | Policy

Copyright@Ministry of Land, Infrastructure, Transport and Tourism



Ministry of Land, Infrastructure, Transport and Tourism